






MAINS ISOLATED VARIAC




ISOLATED OUTPUT
0 – 250VAC 1000VA


FUSE 4AT



MAINS IN



POWER



ON

OFF

PROTECTION



MEES 4

